

This guidance document is advisory in nature but is binding on an agency until amended by such agency. A guidance document does not include internal procedural documents that only affect the internal operations of the agency and does not impose additional requirements or penalties on regulated parties or include confidential information or rules and regulations made in accordance with the Administrative Procedure Act. If you believe that this guidance document imposes additional requirements or penalties on regulated parties, you may request a review of the document.

Hazardous & General Waste Tips for Ethanol Plants

This guidance document is intended to provide basic information about waste management for ethanol plants. The regulations applying to this topic can be found in Nebraska [Title 128 – Hazardous Waste Regulations](#). All waste generators are required to perform a waste determination to see if their waste streams are a hazardous waste.

The following are examples of waste streams that should be considered as potential hazardous wastes that will require a waste determination:

- Still bottom sludges
- Sludges from floor drains, sand pits, oil and water separators, etc.
- Wastewater treatment sludges
- Strong acids or bases (for example: acid hydrolysis processes)
- Spent oils not managed as used oil as provided for under Title 128, Chapter 7
- Fusel oil and related distillation compounds that do not meet the comparable / syngas fuel exclusion (Title 128, Chapter 3 §018) or are not byproducts exhibiting a hazardous waste characteristic being reclaimed (Title 128, Chapter 2 §003.03C)
- Spent solvents or wastewater from azeotropic distillation processes
- Secondary materials from ethanol production
- Tube and vessel cleaning wastes (boilers and reaction vessels)
- Fluorescent light tubes and Compact Fluorescent Lamps
- High Intensity Discharge lamps
- Parts washer solvents, sludges, or filters
- Empty or unusable aerosol cans
- Paint wastes including spent paint solvents
- Rag and wipes not managed under a rag laundering contract
- Batteries
- Computer monitors
- Cleaning products

Upset Considerations

Plan ahead for large waste generation events. Ensure that the facility has the storage capacity to contain overage amount of thin stillage. If wet distillers grain is stored on a wet cake pad before transport, ensure that the pad has suitable containment capacity for overage amounts. It is recommended to have contingency plans in place for large waste generation events.

RESOURCES:

- NDEE Home Page <https://dee.nebraska.gov/>

Contacts:

- NDEE Main Number (402) 471-2186
- NDEE Toll Free Number (877) 253-2603
- NDEE Hazardous Waste Compliance Assistant (402) 471-8308
- Email questions to: NDEE.moreinfo@nebraska.gov

NDEE Publications:

- Guidance Document – Comparison of Hazardous Waste Generator Requirements
- Guidance Document – Waste Determinations & Hazardous Waste Testing
Guidance documents are available on the NDEE Home Page under “Forms”, “Publications, Grants & Forms”.
- [Title 128 – Nebraska Hazardous Waste Regulations](#)
Titles are available on the NDEE Home Page under “Resources and Services”, “Laws & Regulations”, “Rules & Regulations”.

Produced by: Nebraska Department of Environment and Energy, P.O. Box 98922, Lincoln, NE 68509-8922; phone (402) 471-2186. To view this, and other information related to our agency, visit our web site at <https://dee.nebraska.gov/>.